

Appendix 2- Section 19- Actions Outstanding – South Kesteven District Council (SKDC)

Section 19 Reference	Location	Recommendations	Update
S19-337	Grantham – Hazelwood Drive	<p>Task 4 – Anglian Water (AW) and owner of the pond to consider undertaking checks on capacity of pond and how levels in the pond affect the connecting AW surface water system on Hazelwood Drive and ensure the drainage system can perform to its design standard.</p> <p>Parties would need to define design capacity of the system and ensure a management plan is in place to sustain this in the future.</p> <p>Lincolnshire County Council (LCC) as Lead Local Flood Authority (LLFA) to collaborate with these parties to help with this action.</p>	No direct action from SKDC
S19-803	High Dyke, Ancaster	<p>Task 3 - LCC as LLFA, in collaboration with SKDC should consider working with relevant landowners to determine the ownership of the drainage ditch and encourage riparian landowner responsibility for managing flood risk on their land.</p>	Riparian land ownership status is being explored
S19-852	Ancaster	<p>Task 2 – Following works undertaken to the watercourse by the Witham First District Internal Drainage Board and the riparian owner, LCC and SKDC should consider exploring what, if any, options exist to further reduce the risk of flooding to properties in Ancaster.</p>	

Appendix 2- Section 19- Actions Outstanding – South Kesteven District Council (SKDC)

Section 19 Reference	Location	Recommendations	Update
S19-862	Aslackby	Task 2 – SKDC should continue to regularly inspect the condition of the Aslackby ordinary watercourse, maintaining the channel and removing potential blockages as required.	Completed – on annual works program
S19-899 / S19 865	Pointon	<p>Task 1 - SKDC should consider reestablishing the full extent of their maintenance programme on the ordinary watercourse north of West Road. This should extend to include the diversion channel previously constructed which flows under High Street to the north of the affected properties.</p> <p>Following completion of any required maintenance, LCC as the LLFA, in collaboration with SKDC, should consider undertaking a level survey on watercourses within Pointon to better understand the impact any culverts may be having on the natural flow of water alongside identifying those areas whereby out of channel flows are more likely to occur.</p> <p>Subject to the outcome of this level survey, the relevant parties concerned should consider exploring what, if any, feasible and proportionate opportunities exist to either minimise the risk of out of channel flows or ensure the natural onward flow of water through Pointon.</p>	<p>Ongoing – 90% completed.</p> <p>Watercourse full reinstated. Relief dyke most completed awaiting signed easement to enable final works to be completed.</p>

Appendix 2- Section 19- Actions Outstanding – South Kesteven District Council (SKDC)

Section 19 Reference	Location	Recommendations	Update
S19-870	Tallington	Task 1 - It is recommended that AW, LCC, and SKDC consider supporting a partnership funded project to repair / refurbish the surface water sewer that runs along Main Road to Searsions Close and/ or to explore what other opportunities may exist to reduce the risk of surface water flooding in Tallington.	<p>Ongoing</p> <p>A working group was established including LCC AW and SKDC.</p> <p>A review of the drainage systems around and within Billingborough has identified mixed systems with different agencies responsible for assets. AW have reviewed the foul system and identified 2 sections that need repair works. LCC has identified mixed highways surface drains and riparian enforcement needs. SKDC is assisting with identified riparian assets and the possible reconnection of highway to land drainage.</p>

Appendix 2- Section 19- Actions Outstanding – South Kesteven District Council (SKDC)

Section 19 Reference	Location	Recommendations	Update
S19-923	Stamford	Task 4 – SKDC should consider further investigating what measures could be taken to intercept surface water flows from surrounding council housing before it ponds around the flooded property on York Road. Options could include installing intervening drainage on the access path which serves the property.	Discussions are ongoing with other relevant authorities
S19-984	Grantham – Belton Lane	<p>Task 2 - The residents of Belton Lane, with support from SKDC and / or the Lincolnshire Local Resilience Forum (LLRF), should consider producing a flood action plan to ensure that they are suitably prepared should flooding occur again in the future.</p> <p>Task 3 – Consideration should be given by the Environment Agency in collaboration with partner risk management authorities to explore opportunities to reduce the future risk of flooding from the River Witham. Options include the lowering of ground levels along the pathway at the northern banks of the River Witham to create additional storage capacity at Queen Elizabeth Park</p>	<p>Support has been offered to the affected residents. Grantham Town Council are creating a Community Resilience Plan which will include this area, the potential for flooding and mitigating actions.</p> <p>The Environment Agency are exploring opportunities to remodel this area. Once this work is completed conversations are to take place between the EA and SKDC.</p>

Appendix 2- Section 19- Actions Outstanding – South Kesteven District Council (SKDC)

S19-994	Grantham – Tennyson Avenue	Task 3 – SKDC should continue to engage with riparian owners of the ordinary watercourse to the rear of the affected properties on Tennyson Avenue to ensure that the watercourse is maintained and able to intercept flows originating from the adjacent agricultural land.	Ongoing – SKDC's section cleared and riparian owner contacted for works
---------	----------------------------	--	---