



Red = Failed perforated pipework to be replaced with new 100mm perforated pipe surrounded in 10mm shingle

Attenuation tank to be emptied and checked

Black = New 100mm perforated pipe to be added surrounded in 10mm pea shingle.

Blue = Existing pipework cleansed and now fully functional. No work required

Work to be carried out in small sections to minimize disruption, work will be halted if weather deteriorates to prevent the site becoming a mess. 4-5 weeks